

N900 (RX51) Main Circuit Block Diagram

- Connection through PCB contact(s)
- Junction with branch
- Crossing of separate connections
- N signals on connection/branch
- blue: I2C bus

